

Series / Serie / Numéro de série / Serie / Serie

Date / Datum / Date / Fecha / Dato

Maj 1993

## SAILOR HF DSC MODEM RM2150 OG RM2151

### Lejlighedsvis besværligt opkald

Vi har konstateret, at opkald til en skibsstation med et selcall nummer, hvori andet ciffer er 0, kan være besværligt.

Der er foretaget en rettelser i softwaren, således at dette problem nu er løst.

Ny software version 1.34  
S.P. nr. 727841

Den nye software arbejder sammen med version 1.31 i Message Terminal H2098, hvilket er uændret. Det anbefales, at softwaren skiftes ved først givne lejlighed.

Ny software version 1.34 kan bestilles uden beregning hos S.P. Radio A/S, mod oplysning om serienummer på den enhed, hvor softwaren skal skiftes.

May 1993

## SAILOR HF DSC MODEM RM2150 AND RM2151

### Occasional difficult call

We have found that calls to a ship station with a selcall number, in which second digit is 0, can be difficult.

A correction in the software has been made so that this problem is now solved.

New software version 1.34  
S.P. No. 727841

The new software works together with version 1.31 in Message Terminal H2098 which is unchanged. We recommend that the software is changed at the first opportunity.

New software version 1.34 can be ordered free of charge at S.P. Radio A/S, against information about serial number of the unit in which the software is to be replaced.



Please file this information in the service-portfolio we have sent you.

Bitte archivieren Sie diese Mitteilung in der Kundendienstmappe, die wir Ihnen gesandt haben.

Nous vous prions de bien vouloir classer ce document dans le dossier bleu qui vous a été envoyé à cet effet.

Sivanse archivar esta información en la cubierta de servicio que les hemos enviado a Ustedes.

De bedes venligst arkivere denne meddelelse i den tilsendte servicemappe.

A/S S. P. RADIO  
Aalborg - Denmark